

UNION CARBIDE CHEMICALS & PLASTICS COMPANY INC.
Specialty Chemicals Division Sistersville, WV
Organosilicon Products*Systems*Services

May 21, 1990

Memorandum to: R. E. Tuttle

xc: E. P. Tech Staff
Shift Coordinators
PCB File


Re: PCB Action Report

The following PCB equipment was removed from service and placed into storage for disposal on May 16, 1990:

Plt. ID No. (Tag #)	Manufacturer and Type	Serial Number	Voltage	kVAR/ Unit	Qty. of Fluid (gals)
1	Sprague 2043 PFD	54259	480	20	2.1
2	Sprague 2043 PFD	54325	480	20	2.1
3	Sprague 2043 PFD	52956	480	20	2.1
52	Sprague 2043 PFD	54723	480	20	2.1

Additional comments:

Capacitors 1,2 and 3 were placed into drum number 10 and capacitor 52 was placed in drum number 11. The unloading bay of the Silicon Grinding Building is the current storage area for PCBs.


J. A. Selnekovic

JAS/pcb

MPM000819

EPA005141